Division of Health Service Regulation

(X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING FCL073014 02/09/2016 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1025 RIDE ROAD **TOUCH OF LOVE FAMILY CARE HOME** ROXBORO, NC 27573 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 000 Initial Comments C 000 Report by Glenn Hoppin DHSR Construction Section conducted a Biennial Survey on February 09, 2016 from 12:00pm unitl 1:30pm at the above referenced facility. DHSR records indicate the home was first licensed on March 23, 2007 as a Family Care Home for six ambulatory Residents (able to evacuate and respond without any physical or verbal assistance during a fire or other emergency.) Based on this information we are requiring the home to maintain compliance with the following: the 2005 Rules 10A NCAC 13G for Family Care Homes and the 2006 North Carolina State Building Code -Section 421.2 - Residential Care Homes. At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows: C 174 Building Equipment Maintained Safe, Operating C 174 SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE **EQUIPMENT** (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: Observations revealed that the kitchen exhaust fan was not working at the time of the survey. Have a qualified technician repair or replace the exhaust fan. Provide copies of invoices to the DHSR Construction section when this repair is complete.

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE	(X3) DATE SURVEY COMPLETED	
		FCL073014		B. WING		02/0	09/2016	
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE								
TOUCH OF LOVE FAMILY CARE HOME 1025 RIDE ROAD ROXBORO, NC 27573								
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE		

6899

Division of Health Service Regulation STATE FORM